

---

Subject: MIO 2882, replace capacitors in analog section  
Posted by [roastmash](#) on Mon, 11 Nov 2019 13:20:25 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

I'm starting to get a few chirps and discharge type sounds and after my external preamps spent some time with the tech I'm starting to think some of the gremlins might be coming from the analog section of the 2882. Just wondering about which caps need replacing, their values, and if there are any other upgrades or maintenance things I should take care of while it's in for a tune up. Kudos to MH for a product with such a long lifespan that this is even an issue!!

---