
Subject: Plugin glitch and dropouts + preamp clipping
Posted by [christopheA](#) on Fri, 04 Dec 2020 09:35:29 GMT
[View Forum Message](#) <> [Reply to Message](#)

Has anyone had a similar experience?
Any tips?

(i tried using the mailing list but my message didn't appear ... or what am i doing wrong mailing to MobileIO@music.vt.edu ???)

on several occasion i had a glitch when using an EQ (6 band on a channel)
and a dropout when changing a parameter in a limiter on a bus

the glitch and dropouts are only on the mix and not on the individual channel

higher input levels do produce audible distortion, far beneath clipping.
Meters on MIO and NUENDO do not display clipping but there's an audible distortion and crackling noise

the glitch on the EQ is a momentary squeaking noise (not full scale but loud and clearly visible on the waveform for 0,5 sec)

i'm recording 8 channels direct + A masterbus (for a live mix) to Nuendo 10

unit is a recent ULN8

I updated to the last 3D PB + updated firmware
using MH link/cat5

USB is set to ignore always in discovery

Mac Mini 2018 running Mojave (spotlight is disabled, no other programs running)

Nuendo 10 with high Buffer (basically just as a recorder (no plugins used/ straight playback back to MIO)

MIO DSP never exceeds 20%

thanks

Christophe

Subject: Re: Plugin glitch and dropouts + preamp clipping
Posted by [christopheA](#) on Tue, 26 Jan 2021 20:13:27 GMT
[View Forum Message](#) <> [Reply to Message](#)

Bump

After 2 months of trying to find a solution i am still encountering problems when I use plugins in MIO (same as described in above post)

Please let me know if anyone has any similar experience or a solution

I need to expand my setup soon to add another 16 inputs and would like to do so with confidence

Ps: I submitted a ticket and have been in touch with support but no luck so far.

Best
