

---

Subject: Re: ATMOS ROOM CORRECTION AND FOLD DOWNS

Posted by [demetrievidox](#) on Wed, 13 Jul 2022 07:53:07 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thank you for all the details, this was very helpful.

1- the to host pre 9 -10 issue got resolved only by selecting 9 and 10 as a direct out on some other strip and then un-assigning it.. then they showed up again in the to host as available.. bug but not sure how to recreate it.. will monitor

2- all work for me is 48k 24b- and even with a basic stereo mixing setup..only 5 input strips with no plugins or graph inserts only direct outs to host record, 0 auxes, 0 buses, and a stereo monitor source and output (2 mono sonic eq for room eq) ... I'm already running at 50% DSP! how is that possible.. not even using anything hardly.. 2 mono eq's. coming from an antelope audio interfaces with DSP I always was impressed with how much DSP I had available.. this box seems to not even have enough for a small track count 48k session.

I built a basic music tracking session with 20 tracks total i couldnt even get 1 channelstrip plugin per track.. I was only only able to get about 13. can't even accomplish the basics i need.

3. i'm looking forward to talking to someone from support about some of these issues i'm having.

thanks again i really appreciate you taking time to help me. cheers

---