
Subject: MH 2882 headroom issues at +4dBu setting
Posted by [Mattias](#) on Sun, 06 Jan 2013 15:02:31 GMT
[View Forum Message](#) <> [Reply to Message](#)

Hi, I'm having a problem driving the 2882 interface when inputs are set at the +4dBu setting with input gain set at zero. When the interface is set up like this my SPL Dynamaxx and also my API style preamps seems to lose al of their headroom and start to distort way to early. Is this normal?

All the best
// Mattias

Subject: Re: MH 2882 headroom issues at +4dBu setting
Posted by [Mattias](#) on Wed, 09 Jan 2013 13:18:30 GMT
[View Forum Message](#) <> [Reply to Message](#)

Anyone?

Subject: Re: MH 2882 headroom issues at +4dBu setting
Posted by [Allen](#) on Wed, 09 Jan 2013 20:03:54 GMT
[View Forum Message](#) <> [Reply to Message](#)

What happens if you turn down the output gain of your out board gear or the input gain of the 2882?
