

---

Subject: ULN-2 : Headphone pot stereo discrepancy?

Posted by [BoogieMonsta](#) on Sun, 01 Jun 2014 22:08:14 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi again,

Another issue I'm having requires another topic I presume, so here goes :

Not sure whether this is normal or not... But on my ULN-2, as I turn the headphones pot up and down, the stereo image moves slightly left and right. It's definitely enough to throw me off though and I don't feel like I can trust it for my pans!!

I can't say whether or not it's also the case with the monitor pot, my monitoring situation not being accurate enough where I'm at right now.

I know a workaround would be to leave the headphones pot all the way up, and control the volume via Monitor Control (and possibly invest in that USB controller for it, then)... But I'm secretly hoping that I'm doing something wrong, or that this could be fixed somehow...!

Thanks in advance for the insights!

B.

---

---

Subject: Re: ULN-2 : Headphone pot stereo discrepancy?

Posted by [p-tong](#) on Thu, 20 Nov 2014 18:00:04 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Same problem here.(both monitor pot and headphone pot)

---