
Subject: ULN-2 suddenly cuts amp power (volume)
Posted by [zootermac](#) on Thu, 22 Sep 2016 08:50:30 GMT
[View Forum Message](#) <> [Reply to Message](#)

Hello

I'm using guitar DI > ULN-2 > Torpedo reamp > amp > loadbox > back to ULN-2. After some playing the power just drops out, theres still sound but it's like half as loud. I've experienced it coming back in the same sitting after a few minutes. When I turn everything on the following day there is initially full power.

The reasons I think the ULN-2 is the culprit is

- A. There is no overheat warning on the Torpedo reamp/loadbox
- B. Amp tunes are OK since it turns on fine the following day or after some time.
- C. After the power dropout, the gain on the ULN-2 no longer makes a difference.

It's as if it's a safety mechanism. Next time I'll monitor if I'm clipping the sound card too much, could it be possible that it automatically cuts out after being clipped too long?

Any other ideas?

Much appreciated. Thank you
