

---

Subject: Hissing Genelec 8010as when plugged into 2882 and ULN-2

Posted by [Kroy](#) on Fri, 08 Oct 2021 05:05:59 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I have an older generation 2882 and ULN-2.

I just bought a pair of Genelec 8010a active monitors and there is a noticeable hiss coming from both speakers when they are plugged in to both 2882 and ULN-2.

I am using balanced XLR (Speaker) -> Jack (Audio Interface).

The Genelecs have a -10db switch on the back and even with that activated the hiss is noticeable.

With it OFF the hiss is really loud.

Previously I've been using a pair of Proac Studio 100s with a Hafler P3000 power amp, with no hissing issues at all.

I was wondering if there's any workaround for this.

eg Would a hum isolator like the Art DTI Hum Eliminator 2 work?

---

Subject: Re: Hissing Genelec 8010as when plugged into 2882 and ULN-2

Posted by [Riley Casey](#) on Sun, 17 Oct 2021 22:16:56 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Sounds like a gain structure issue right oof the bat.

---