

---

Subject: 2882 DSP USAGE

Posted by [whiskeynipple0088](#) on Tue, 30 Jun 2015 17:59:11 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi all - first time here and new to the MH family.

I love my 2882 +DSP with license. Definitely one of those 'why did I wait so long moments'.

Im recording into logic pro thru the MH 2882 at 88.2khz. (10.10.3 - LPX 10.1.1)

I am routing individual tracks from Logic back to 2882 via firewire 1 thru 18 and summing in the MH box.

I am placing effects (mostly channel strip) and charecter on about 12 tracks at this point.

I have noticed the meters stop working on some tracks and there is audible distortion.

DSP usage shows 147% and when plugin is placed on master buss it shows 10% and audible distortion get severe. And I am no where close to done adding plugins for mixing.

(Once I remove some plugins - all is back to normal.)

Is this normal?

Am I maxing out the DSP already?

Is there a work around?

thanks