

---

Subject: Windows 10 - What is working or not ?

Posted by [MatthieuTibi](#) on Mon, 18 Jan 2021 10:34:14 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hello,

I'm thinking of switching my home theater from Mac OS to Windows.

I own a 2d 2882, I'm about to upgrade in 3d (with the SPDIF/ADATx2 EdgeCard)

I have a few questions before, I've searched before here :

[https://mhsecure.com/3d\\_Early\\_Access/release\\_notes/pb10-138.html](https://mhsecure.com/3d_Early_Access/release_notes/pb10-138.html)

But everything is not clear to me.

- I need 6 analogs outputs (5.1 monitoring)
- I need several inputs : 6 analogs, 2 optical spdif, 1 optical ADAT (6 channels on that input)
- I need an ASIO driver, I can use ASIO4ALL.

If I understand well, I won't have a config panel with windows, but I can connect the 2882 in USB and do the setup with a Mac in RJ45 (which is fine to me).

How many Inputs and Outputs will windows see in USB ?

If my counts are corrects, I need 6 outputs and 16 inputs.

Will it be ok with Asio4all ?

Is there any date for a complete windows driver ?

Thanks !

Matthieu