
Subject: ULN2 not working with Mac Mini and mavericks 10.9.5

Posted by [Vladturn](#) on Wed, 02 Sep 2015 13:08:02 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hi,

I have recently purchased a Mac Mini late 2012 corei7 to speed up my work. For several years I have used a Macbook pro 2009 and ULN2card +dsp with no problems at all. The problem is the Mac Mini does not see or recognise the ULN2 card , just the power lamp blinking faintly.

I have restored my entire OSX Mavericks from the working Macbook pro to the Mac Mini from a backup disk and even installed the MIO drivers once again just to make sure. I have tried changing the firewire cables (witch work with the Macbook) but no luck. Could it be I am not using a power supply,

because I did not have to do that on the Macbook? Any clues? This is annoying.
