

---

Subject: Do i need a firmware update?

Posted by [mutascan](#) on Wed, 10 Feb 2016 01:26:35 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hello,

i recently installed the latest version of mio console after updating to EL CAPITAN.

Now, when i open the mio console mixer and click at the top (Analog1) on the first channel, i see: (Mono) OFFLINE ULN2+DSP/Serial # and i don't see (or hear) incoming signal in mio's mixer... altho the potentiometer on the front panel of the card shows incoming sound.

Does this mean i need to update the firmware? And if so, where can i download it?

Thanks in advance

---