

---

Subject: New MIOConsole not working

Posted by [Torsten Lang](#) on Wed, 02 Nov 2022 09:12:41 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I just installed the new console, driver, firmware (even though there was nothing shown that told me that the firmware was actually installed) on my 2014 macbook pro with OSX 10.14.6.

The hardware is now not recognized by the console anymore.

Anyone else has this problem?

---