

---

Subject: ULN-2 Hardware Routing

Posted by [dustpandave](#) on Tue, 10 Dec 2013 10:42:21 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi guys

I would like to my Fractal Audio Axe-fx to re amp a dry DI guitar recording in my PT session.

Is there a way to use Analog 1 and 2 as separate outputs to Monitor 1 and 2

i.e. make analog 1 and 2 theoretically function as Outputs 3-4?

Thus having a 4 output ULN-2? or is it only possible to have 1 stereo output with the ULN?

Ideally I would like to send the dry guitar track out of output 3 ("physically - analog 1 on unit") via hardware insert or output bus in PT and have that go out the halo into the axe-fx and then back into Preamp 1 and print it into Pro Tools...

is this not possible? i have had a look at the MIO mixer and it does not seem so but maybe im missing something.

I have tried to just mute everything and send out of analog 1 (which is currently linked to Monitor outs) and it just creates a nasty feedback loop or something.

Hope you guys can help!

David

---