
Subject: 2882

Posted by [politicattika](#) on Fri, 05 Sep 2014 17:09:29 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hello, i got a strange issue, my very beloved mh interface shows inputs clipping without anything connected, no audio coming out??? The hardware shows the input clipping as well. So i'm running a macbook pro intel core duo 2.8ghz 8 gb ram, on Maverick OS 10.9.4 i've uploaded a pic to have a look, my version of Mio console v5.6.04.215.

File Attachments

1) [Screen Shot 2014-09-05 at 18.05.57.png](#), downloaded 1043 times

Subject: Re: 2882

Posted by [bj](#) on Fri, 05 Sep 2014 18:40:06 GMT

[View Forum Message](#) <> [Reply to Message](#)

Please open a support ticket for help with this:

<https://mhsecure.com/support>
