
Subject: ULN-2 connects as an "Unknown Device"
Posted by [Jeremiah](#) on Mon, 11 May 2015 22:44:51 GMT
[View Forum Message](#) <> [Reply to Message](#)

When powering on a ULN-2 with a known working power supply the "c" light and other states below it stay dark. I've tried two power supplies with and without it plugged in to firewire; two Macs (10.5.8 PowerPC and 10.10.3 Intel): multiple versions of console: two drivers (current for the hardware): and confirmed that both systems recognize my ULN-2 Expanded + DSP. It shows as an "Unknown Device" under Firewire in System Information/System Profiler.

Are there any hardware resets for the ULN-2? Any suggestions for things to try? I just picked it up used and it worked intermittently so I thought it was a software issue. I can return it but I'd like to explore my options before doing so. I was planing to upgrade it to the 2D card but I am skeptical that it would resolve this issue.

Status

Power: lit

Firewire: lit (even when not connected with Firewire)

Locked: lit

S/R

96: lit

Clock

INT: lit

Digital I/O

AES: slightly lit

Locked: dark
