
Subject: Phasing on Main Output's ULN-8 3d
Posted by [muscape](#) on Fri, 02 Oct 2020 09:23:09 GMT
[View Forum Message](#) <> [Reply to Message](#)

Hi,

so i have an issue with the main outs on the ULN-8 3d.

Sometimes i am hearing a phasing noise which is like a sweep. It goes from let's say 2k to 10k. I can't reproduce it every time. Don't know where it comes from? Another thing is, that the levels are not the same between the L and R Channel.

I didn't change the setup in the Studio. Just upgraded to a new MBP 2017 from a 2011 and a new ULN-8 3d.

ULN-8 3d last update
Neumann KH310d
MBP 2017 OSX 10.14.6

Thank you...

Subject: Re: Phasing on Main Output's ULN-8 3d
Posted by [bj](#) on Fri, 02 Oct 2020 18:04:22 GMT
[View Forum Message](#) <> [Reply to Message](#)

This does not sound familiar. I think you should open a support ticket:

<https://mhsecure.com/support>
